



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	163	<b>Date:</b>	9/27/2004	<b>MeterBasin:</b>	01_WRR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6211		Benhurst	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 91

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0927-2004\T-2\PLAYER\_B\B\_2004\_0927Image0091.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 23  
Setup No. 3  
163

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 9/27/04	Start Time: 1045
Crew: T2	Street Location: Benhurst Rd		
US MH: 1522457	DS MH: 1520998	Number of Segments: 6	Test Length: 1099'
Plugged US: <input checked="" type="radio"/> N	Plugged DS: <input checked="" type="radio"/> N	# of Blowers: 1 (2) 3	Ground: <input checked="" type="radio"/> Dry Moderate Wet
Plugs Removed? <input checked="" type="radio"/> N	Recorder: Bob Blank	Comments:	

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

**CREW COMMENTS**

Last Revised 9/16/2004  
Leader Form

Sketch No: 163

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\163.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	163	<b>Date:</b>	9/27/2004	<b>MeterBasin:</b>	01_WRR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6210		Benhurst	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 92

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0927-2004\T-2\PLAYER\_B\B\_2004\_0927Image0092.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

## SMOKE TESTING OBSERVATION SUMMARY

# Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM

Page 1 of 2  
Smoke Set No. 23  
Setup No. 3  
163

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 9/27/04	Start Time: 1045
Crew: T2	Street Location: Benhurst Rd		
US MH: 1522457	DS MH: 1520978	Number of Segments: 6	Test Length: 1099'
Plugged US: <input checked="" type="radio"/> Y <input type="radio"/> N	Plugged DS: <input checked="" type="radio"/> Y <input type="radio"/> N	# of Blowers: 1 2 3	Ground: <input checked="" type="radio"/> Dry <input type="radio"/> Moderate <input type="radio"/> Wet
Plugs Removed? <input checked="" type="radio"/> Y <input type="radio"/> N	Recorder: Bob Blank	Comments:	
<b>FIELD SKETCH</b> (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)			

Field sketch showing manholes, streets, and blower locations. Streets include Benhurst Rd, Verdene Ave, Strathmore Ave, and Western Ave. Manholes are labeled with IDs like 1522457, 1522458, 1522460, 1520978, 1520976, and 1520979. Distances between manholes are marked: 162', 148', 265', 99', and 252'. A north arrow is present in the top left corner.

**CREW COMMENTS**

Last Revised 9/16/2004

Leader Form

Sketch No: 163

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\163.tif

**Image Status:** Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	163	<b>Date:</b>	9/27/2004	<b>MeterBasin:</b>	01_WRR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6212		Benhurst	ROAD
<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	16
<b>Comments:</b>			

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 93

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0927-2004\T-2\PLAYER\_B\B\_2004\_0927Image0093.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

## SMOKE TESTING OBSERVATION SUMMARY

# Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 23  
Setup No. 3

163

BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 7/27/04	Start Time: 1045
Crew: T2	Street Location: Benhurst Rd		
US MH: 1522457	DS MH: 1520998	Number of Segments: 6	Test Length: 1099'
Plugged US: (Y) N	Plugged DS: (Y) N	# of Blowers: 1 (2) 3	Ground: (Dry) Moderate Wet
Plugs Removed? (Y) N	Recorder: Bob Blank	Comments:	
FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)			

Last Revised 9/16/2004

Leader Form

Sketch No: 163

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\163.tif

**Image Status:** Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	163	<b>Date:</b>	9/27/2004	<b>MeterBasin:</b>	01_WRR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	4	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2934		Bartol	AVE

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 94

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0927-2004\T-2\PLAYER\_B\B\_2004\_0927Image0094.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

## SMOKE TESTING OBSERVATION SUMMARY

# Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM

Page 1 of 2  
Smoke Set No. 23  
Setup No. 3  
163

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 9/27/04	Start Time: 1045
Crew: T2	Street Location: Benhurst Rd		
US MH: 1522457	DS MH: 1520978	Number of Segments: 6	Test Length: 1099'
Plugged US: <input checked="" type="radio"/> Y <input type="radio"/> N	Plugged DS: <input checked="" type="radio"/> Y <input type="radio"/> N	# of Blowers: 1 2 3	Ground: <input checked="" type="radio"/> Dry <input type="radio"/> Moderate <input type="radio"/> Wet
Plugs Removed? <input checked="" type="radio"/> Y <input type="radio"/> N	Recorder: Bob Blank	Comments:	
<b>FIELD SKETCH</b> (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)			

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

Last Revised 9/16/2004

Leader Form

Sketch No: 163

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\163.tif

**Image Status:** Image found and displayed.

**NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.**





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	163	<b>Date:</b>	9/27/2004	<b>MeterBasin:</b>	01_WRR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	5	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
3001		W Strathmore	AVE
<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0
<b>Comments:</b>			

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 97

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0927-2004\T-2\PLAYER\_B\B\_2004\_0927Image0097.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

## SMOKE TESTING OBSERVATION SUMMARY

# Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 23  
Setup No. 3

163

BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 7/27/04	Start Time: 1045
Crew: T2	Street Location: Benhurst Rd		
US MH: 1522457	DS MH: 1520998	Number of Segments: 6	Test Length: 1099'
Plugged US: (Y) N	Plugged DS: (Y) N	# of Blowers: 1(2)3	Ground: (Dry) Moderate Wet
Plugs Removed? (Y) N	Recorder: Bob Blank	Comments:	
FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)			

Last Revised 9/16/2004

Leader Form

Sketch No: 163

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\163.tif

**Image Status:** Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	164	<b>Date:</b>	9/27/2004	<b>MeterBasin:</b>	01_WRR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	4	<b>Priority CCTV:</b>	

<b>House Number</b>	6105	<b>Street Prefix:</b>		<b>Street Name:</b>	Benhurst	<b>Street Type:</b>	ROAD
<b>Source Type:</b>	02= Service Line	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>			
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	25				
<b>Comments:</b>							

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 96

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0927-2004\T-2\PLAYER\_B\B\_2004\_0927Image0096.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.




# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland


## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 23  
Setup No. 4  
114

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: <u>7/27/04</u>	Start Time: <u>1300</u>
Crew: <u>T2</u>	Street Location: <u>Benhurst Rd</u>		
US MH: <u>1522062</u>	DS MH: <u>1520996</u>	Number of Segments: <u>8</u>	Test Length: <u>1132'</u>
Plugged US: <u>Y</u> <input checked="" type="radio"/> <u>N</u>	Plugged DS: <u>Y</u> <input checked="" type="radio"/> <u>N</u>	# of Blowers <u>1(2)3</u>	Ground: <u>Dry</u> Moderate Wet
Plugs Removed? <u>Y</u> <input checked="" type="radio"/> <u>N</u>	Recorder: <u>Bb Bink</u>	Comments:	

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)



**CREW COMMENTS**

Last Revised 9/16/2004Leader Form

Sketch No: 164

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\164.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	164	<b>Date:</b>	9/27/2004	<b>MeterBasin:</b>	01_WRR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	4	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6106		Benhurst	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 98

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0927-2004\T-2\PLAYER\_B\B\_2004\_0927Image0098.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.




# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland


## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 23  
Setup No. 4  
114

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: <u>7/27/04</u>	Start Time: <u>1300</u>
Crew: <u>T2</u>	Street Location: <u>Benhurst Rd</u>		
US MH: <u>1522062</u>	DS MH: <u>1520996</u>	Number of Segments: <u>8</u>	Test Length: <u>1132'</u>
Plugged US: <u>Y</u> <input checked="" type="radio"/> <u>N</u>	Plugged DS: <u>Y</u> <input checked="" type="radio"/> <u>N</u>	# of Blowers <u>1(2)3</u>	Ground: <u>Dry</u> Moderate Wet
Plugs Removed? <u>Y</u> <input checked="" type="radio"/> <u>N</u>	Recorder: <u>Bb Bink</u>	Comments:	

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)



**CREW COMMENTS**

Last Revised 9/16/2004Leader Form

Sketch No: 164

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\164.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	164	<b>Date:</b>	9/27/2004	<b>MeterBasin:</b>	01_WRR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	4	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6107		Benhurst	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 99

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0927-2004\T-2\PLAYER\_B\B\_2004\_0927Image0099.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.




# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland


## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 23  
Setup No. 4  
114

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: <u>9/27/04</u>	Start Time: <u>1300</u>
Crew: <u>T2</u>	Street Location: <u>Benhurst Rd</u>		
US MH: <u>1522062</u>	DS MH: <u>1520996</u>	Number of Segments: <u>8</u>	Test Length: <u>1132'</u>
Plugged US: <u>Y</u> <input checked="" type="radio"/> <u>N</u>	Plugged DS: <u>Y</u> <input checked="" type="radio"/> <u>N</u>	# of Blowers <u>1(2)3</u>	Ground: <u>Dry</u> Moderate Wet
Plugs Removed? <u>Y</u> <input checked="" type="radio"/> <u>N</u>	Recorder: <u>Bb Bink</u>	Comments:	

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)



**CREW COMMENTS**

Last Revised 9/16/2004Leader Form

Sketch No: 164

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\164.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	164	<b>Date:</b>	9/27/2004	<b>MeterBasin:</b>	01_WRR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	4	<b>Setup No:</b>	4	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6119		Benhurst	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 100

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0927-2004\T-2\PLAYER\_B\B\_2004\_0927Image0100.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.




# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland


## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 23  
Setup No. 4  
114

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: <u>7/27/04</u>	Start Time: <u>1300</u>
Crew: <u>T2</u>	Street Location: <u>Benhurst Rd</u>		
US MH: <u>1522062</u>	DS MH: <u>1520996</u>	Number of Segments: <u>8</u>	Test Length: <u>1132'</u>
Plugged US: <u>Y</u> <input checked="" type="radio"/> <u>N</u>	Plugged DS: <u>Y</u> <input checked="" type="radio"/> <u>N</u>	# of Blowers <u>1(2)3</u>	Ground: <u>Dry</u> Moderate Wet
Plugs Removed? <u>Y</u> <input checked="" type="radio"/> <u>N</u>	Recorder: <u>Bb Bink</u>	Comments:	

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)



**CREW COMMENTS**

Last Revised 9/16/2004Leader Form

Sketch No: 164

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\164.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	165	<b>Date:</b>	9/27/2004	<b>MeterBasin:</b>	01_WRR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	5	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2845		Baneberry	Ct
<b>Source Type:</b>	12= MH Frame Seal	<b>Location:</b>	9=Yard-Side
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	50
<b>Severity:</b>			
<b>Comments:</b>			

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 101

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0927-2004\T-2\PLAYER\_B\B\_2004\_0927Image0101.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 23  
Setup No. 5  
165

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 9/27/04	Start Time: 1410
Crew: T2	Street Location: Verdere Ave		
US MH: 1522462	DS MH: 1520985	Number of Segments: 8	Test Length: 1437'
Plugged US: Y (N)	Plugged DS: Y (N)	# of Blowers: 1 (2) 3	Ground: Dry Moderate Wet
Plugs Removed? Y (N)	Recorder: Bob Bink	Comments:	

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

**CREW COMMENTS**

Last Revised 9/16/2004  
Leader Form

Sketch No: 165

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\165.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	165	<b>Date:</b>	9/27/2004	<b>MeterBasin:</b>	01_WRR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	10	<b>Setup No:</b>	5	<b>Priority CCTV:</b>	

<b>House Number</b>	2912	<b>Street Prefix:</b>		<b>Street Name:</b>	W Strathmore	<b>Street Type:</b>	AVE
<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>			
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0				
<b>Comments:</b>							

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 110

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0927-2004\T-2\PLAYER\_B\B\_2004\_0927Image0110.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 23  
Setup No. 5  
165

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 9/27/04	Start Time: 1410
Crew: T2	Street Location: Verdere Ave		
US MH: 1522462	DS MH: 1520985	Number of Segments: 8	Test Length: 1437'
Plugged US: Y (N)	Plugged DS: Y (N)	# of Blowers: 1 (2) 3	Ground: Dry Moderate Wet
Plugs Removed? Y (N)	Recorder: Bob Bink	Comments:	

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 9/16/2004  
Leader Form

Sketch No: 165

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\165.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	165	<b>Date:</b>	9/27/2004	<b>MeterBasin:</b>	01_WRR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	11	<b>Setup No:</b>	5	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2912		W Strathmore	AVE
<b>Source Type:</b>	02= Service Line	<b>Location:</b>	7=Yard-Front
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	9
<b>Severity:</b>			
<b>Comments:</b>			

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 111

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0927-2004\T-2\PLAYER\_B\B\_2004\_0927Image0111.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.




# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 23  
Setup No. 5  
165

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 9/27/04	Start Time: 1410
Crew: T2	Street Location: Verdere Ave		
US MH: 1522462	DS MH: 1520985	Number of Segments: 8	Test Length: 1437'
Plugged US: <input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Plugged DS: <input checked="" type="checkbox"/> Y <input type="checkbox"/> N	# of Blowers: 1 (2) 3	Ground: <input checked="" type="checkbox"/> Dry <input type="checkbox"/> Moderate <input type="checkbox"/> Wet
Plugs Removed? <input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Recorder: Bob Bink	Comments:	

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

**CREW COMMENTS**

Last Revised 9/16/2004Leader Form

Sketch No: 165

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\165.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	165	<b>Date:</b>	9/27/2004	<b>MeterBasin:</b>	01_WRR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	12	<b>Setup No:</b>	5	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2910		W Strathmore	AVE

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 112

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0927-2004\T-2\PLAYER\_B\B\_2004\_0927Image0112.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 23  
Setup No. 5  
165

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 9/27/04	Start Time: 1410
Crew: T2	Street Location: Verdere Ave		
US MH: 1522462	DS MH: 1520985	Number of Segments: 8	Test Length: 1437'
Plugged US: Y (N)	Plugged DS: Y (N)	# of Blowers: 1 (2) 3	Ground: Dry Moderate Wet
Plugs Removed? Y (N)	Recorder: Bob Bink	Comments:	

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

**CREW COMMENTS**

Last Revised 9/16/2004  
Leader Form

Sketch No: 165

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\165.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	165	<b>Date:</b>	9/27/2004	<b>MeterBasin:</b>	01_WRR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	13	<b>Setup No:</b>	5	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2906		W Strathmore	AVE

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 113

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0927-2004\T-2\PLAYER\_B\B\_2004\_0927Image0113.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 23  
Setup No. 5  
165

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 9/27/04	Start Time: 1410
Crew: T2	Street Location: Verdene Ave		
US MH: 1522462	DS MH: 1520985	Number of Segments: 8	Test Length: 1437'
Plugged US: Y (N)	Plugged DS: Y (N)	# of Blowers: 1 (2) 3	Ground: Dry Moderate Wet
Plugs Removed? Y (N)	Recorder: Bob Bink	Comments:	

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

6291

6205

6204

6203

6202

6201

6200

6199

6198

6197

6196

6195

6194

6193

6192

6191

6190

6189

6188

6187

6186

6185

6184

6183

6182

6181

6180

6179

6178

6177

6176

6175

6174

6173

6172

6171

6170

6169

6168

6167

6166

6165

6164

6163

6162

6161

6160

6159

6158

6157

6156

6155

6154

6153

6152

6151

6150

6149

6148

6147

6146

6145

6144

6143

6142

6141

6140

6139

6138

6137

6136

6135

6134

6133

6132

6131

6130

6129

6128

6127

6126

6125

6124

6123

6122

6121

6120

6119

6118

6117

6116

6115

6114

6113

6112

6111

6110

6109

6108

6107

6106

6105

6104

6103

6102

6101

6100

6099

6098

6097

6096

6095

6094

6093

6092

6091

6090

6089

6088

6087

6086

6085

6084

6083

6082

6081

6080

6079

6078

6077

6076

6075

6074

6073

6072

6071

6070

6069

6068

6067

6066

6065

6064

6063

6062

6061

6060

6059

6058

6057

6056

6055

6054

6053

6052

6051

6050

6049

6048

6047

6046

6045

6044

6043

6042

6041

6040

6039

6038

6037

6036

6035

6034

6033

6032

6031

6030

6029

6028

6027

6026

6025

6024

6023

6022

6021

6020

6019

6018

6017

6016

6015

6014

6013

6012

6011

6010

6009

6008

6007

6006

6005

6004

6003

6002

6001

6000

5999

5998

5997

5996

5995

5994

5993

5992

5991

5990

5989

5988

5987

5986

5985

5984

5983

5982

5981

5980

5979

5978

5977

5976

5975

5974

5973

5972

5971

5970

5969

5968

5967

5966

5965

5964

5963

5962

5961

5960

5959

5958

5957

5956

5955

5954

5953

5952

5951

5950

5949

5948

5947

5946

5945

5944

5943

5942

5941

5940

5939

5938

5937

5936

5935

5934

5933

5932

5931

5930

5929

5928

5927

5926

5925

5924

5923

5922

5921

5920

5919

5918

5917

5916

5915

5914

5913

5912

5911

5910

5909

5908

5907

5906

5905

5904

5903

5902

5901

5900

5899

5898

5897

5896

5895

5894

5893

5892

5891

5890

5889

5888

5887

5886

5885

5884

5883

5882

5881

5880

5879

5878

5877

5876

5875

5874

5873

5872

5871

5870

5869

5868

5867

5866

5865

5864

5863

5862

5861

5860

5859

5858

5857

5856

5855

5854

5853

5852

5851

5850

5849

5848

5847

5846

5845

5844

5843

5842

5841

5840

5839

5838

5837

5836

5835

5834

5833

5832

5831

5830

5829

5828

5827

5826

5825

5824

5823

5822

5821

5820

5819

5818

5817

5816

5815

5814

5813

5812

5811

5810

5809

5808

5807

5806

5805

5804

5803

5802

5801

5800

5799

5798

5797

5796

5795

5794

5793

5792

5791

5790

5789

5788

5787

5786

5785

5784

5783

5782

5781

5780

5779

5778

5777

5776

5775

5774

5773

5772

5771

5770

5769

5768

5767

5766

5765

5764

5763

5762

5761

5760

5759

5758

5757

5756

5755

5754

5753

5752

5751

5750

5749

5748

5747

5746

5745

5744

5743

5742

5741

5740

5739

5738

5737

5736

5735

5734

5733

5732

5731

5730

5729

5728

5727

5726

5725

5724

5723

5722

5721

5720

5719

5718

5717

5716

5715

5714

5713

5712

5711

5710

5709

5708

5707

5706

5705

5704

5703

5702

5701

5700

5699

5698

5697

5696

5695

5694

5693

5692

5691

5690

5689

5688

5687

5686

5685

5684

5683

5682

5681

5680

5679

5678

5677

5676

5675

5674

5673

5672

5671

5670

5669

5668

5667

5666

5665

5664

5663

5662

5661

5660

5659

5658

5657

5656

5655

5654

5653

5652

5651

5650

5649

5648

5647

5646

5645

5644

5643

5642

5641

5640

5639

5638

5637

5636

5635

5634

5633

5632

5631

5630

5629

5628

5627

5626

5625

5624

5623

5622

5621

5620

5619

5618

5617

5616

5615

5614

5613

5612

5611

5610

5609

5608

5607

5606

5605

5604

5603

5602

5601

5600

5599

5598

5597

5596

5595

5594

5593

5592

5591

5590

5589

5588

5587

5586

5585

5584

5583

5582

5581

5580

5579

5578

5577

5576

5575

5574

5573

5572

5571

5570

5569

5568

5567

5566

5565

5564

5563

5562

5561

5560

5559

5558

5557

5556

5555

5554

5553

5552

5551

5550

5549

5548

5547

5546

5545

5544

5543

5542

5541

5540

5539

5538

5537

5536

5535

5534

5533

5532

5531

5530

5529

5528

5527

5526

5525

5524

5523

5522

5521

5520

5519

5518

5517

5516

5515

5514

5513

5512

5511

5510

5509

5508

5507

5506

5505

5504

5503

5502

5501

5500

5499

5498

5497

5496

5495

5494

5493

5492

5491

5490

5489

5488

5487

5486

5485

5484

5483

5482

5481

5480

5479

5478

5477

5476

5475

5474

5473

5472

5471

5470

5469

5468

5467

5466

5465

5464

5463

5462

5461

5460

5459

5458

5457

5456

5455

5454

5453

5452

5451

5450

5449

5448

5447

5446

5445

5444

5443

5442

5441

5440

5439

5438

5437

5436

5435

5434

5433

5432

5431

5430

5429

5428

5427

5426

5425

5424

5423

5422

5421

5420

5419

5418

5417

5416

5415

5414

5413

5412

5411

5410

5409

5408

5407

5406

5405

5404

5403

5402

5401

5400

5399

5398

5397

5396

5395

5394

5393

5392

5391

5390

5389

5388

5387

5386

5385

5384

5383

5382

5381

5380

5379

5378

5377

5376

5375

5374

5373

5372

5371

5370

5369

5368

5367

5366

5365

5364

5363

5362

5361

5360

5359

5358

5357

5356

5355

5354

5353

5352

5351

5350

5349

5348

5347

5346

5345

5344

5343

5342

5341

5340

5339

5338

5337

5336

5335

5334

5333

5332

5331

5330

5329

5328

5327

5326

5325

5324

5323

5322

5321

5320

5319

5318

5317

5316

5315

5314

5313

5312

5311

5310

5309

5308

5307

5306

5305

5304

5303

5302

5301

5300

5299

5298

5297

5296

5295

5294

5293

5292

5291

5290

5289

5288

5287

5286

5285

5284

5283

5282

5281

5280

5279

5278

5277

5276

5275

5274

5273

5272

5271

5270

5269

5268

5267

5266

5265

5264

5263

5262

5261

5260

5259

5258

5257

5256

5255

5254

5253

5252

5251

5250

5249

5248

5247

5246

5245

5244

5243

5242

5241

5240

5239

5238

5237

5236

5235

5234

5233

5232

5231

5230

5229

5228

5227

5226

5225

5224

5223

5222

5221

5220

5219

5218

5217

5216

5215

5214

5213

5212

5211

5210

5209

5208

5207

5206

5205

5204

5203

5202

5201

5200

5199

5198

5197

5196

5195

5194

5193

5192

5191

5190

5189

5188

5187

5186

5185

5184

5183

5182

5181

5180

5179

5178

5177

5176

5175

5174

5173

5172

5171

5170

5169

5168

5167

5166

5165

5164

5163

5162

5161

5160

5159

5158

5157

5156

5155

5154

5153

5152

5151

5150

5149

5148

5147

5146

5145

5144

5143

5142

5141

5140

5139

5138

5137

5136

5135

5134

5133

5132

5131

5130

5129

5128

5127

5126

5125

5124

5123

5122

5121

5120

5119

5118

5117

5116

5115

5114

5113

5112

5111

5110

5109

5108

5107

5106

5105

5104

5103

5102

5101

5100

5099

5098

5097

5096

5095

5094

5093

5092

5091

5090

5089

5088

5087

5086

5085

5084

5083

5082

5081

5080

5079

5078

5077

5076

5075

5074

5073

5072

5071

5070

5069

5068

5067

5066

5065

5064

5063

5062

5061

5060

5059

5058

5057

5056

5055

5054

5053

5052

5051

5050

5049

5048

5047

5046

5045

5044

5043

5042

5041

5040

5039

5038

5037

5036

5035

5034

5033

5032

5031

5030

5029

5028

5027

5026

5025

5024

5023

5022

5021

5020

5019

5018

5017

5016

5015

5014

5013

5012

5011

5010

5009

5008

5007

5006

5005

5004

5003

5002

5001

5000

4999

4998

4997

4996

4995

4994

4993

4992

4991

4990

4989

4988

4987

4986

4985

4984

4983

4982

4981

4980

4979

4978

4977

4976

4975

4974

4973

4972

4971

4970

4969

4968

4967

4966

4965

4964

4963

4962

4961

4960

4959

4958

4957

4956

4955

4954

4953

4952

4951

4950

4949

4948

4947

4946

4945

4944

4943

4942

4941

4940

4939

4938

4937

4936

4935

4934

4933

4932

4931

4930

4929

4928

4927

4926

4925

4924

4923

4922

4921

4920

4919

4918

4917

4916

4915

4914

4913

4912

4911

4910

4909

4908

4907

4906

4905

4904



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	165	<b>Date:</b>	9/27/2004	<b>MeterBasin:</b>	01_WRR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	5	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2845		Baneberry	Ct

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 102

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0927-2004\T-2\PLAYER\_B\B\_2004\_0927Image0102.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.




# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 23  
Setup No. 5  
165

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 9/27/04	Start Time: 1410
Crew: TJ	Street Location: Verdere Ave		
US MH: 1522462	DS MH: 1520985	Number of Segments: 8	Test Length: 1437'
Plugged US: Y (N)	Plugged DS: Y (N)	# of Blowers: 1 (2) 3	Ground: Dry Moderate Wet
Plugs Removed? Y (N)	Recorder: Bob Bink	Comments:	

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

**CREW COMMENTS**

Last Revised 9/16/2004Leader Form

Sketch No: 165

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\165.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.